

Level Box Instruction Manual



Technical Specifications	
Ассигасу	0° and 90° : ±0.1° , the rest : ±0.2°
Resolution	0.05°
Working Range	4×90°
Power Supply	2 ×AAA alkaline battery
Working temperature	32°F to 104°F (0°C to 40°C)
Working Humidity	≤85%

LCD SC	REEN ICONS
ABS	Indicates that the level is working in absolute angle mode
-1-	Indicates that the digital level is calibrating for one direction
-2-	Indicates that the digital level is calibrating for another direction
Erro	Warning of the vertical axis deviation




BUTTON FUNCTION

ON/OFF

1. Press the on/off button once to turn the unit on. To turn off the unit, hold the on/off button for 3 seconds. After approximately 5 minutes of no button press, the unit will shut off. To restart the unit, press the on/off button once.

ZERO

- 1. With the unit on, push the zero button to set the display to zero and to enter the relative measurement mode.
- 2. In relative measurement mode, the "ABS" symbol on the LCD will disappear.
- 3. Relative measurement mode allows the operator to measure the difference between two objects. The absolute mode measures the angle between horizontal plane and the first object. (See Diagram Below)
- 4. To return to (ABS) absolute measurement mode, press the zero one time.



CALIBRATION(Figs as below)


- *The digital level has been pre-calibrated at the factory, The product should only be recalibrated if it has been dropped*
- (1) Place the digital level on a flat and smooth surface, press button ON/OFF and button ZERO at the same time, the calibration mode is activated and "-1-" will be displayed.
- (2) Press button ON/OFF again, "-1-" will flash briefly. Do not move until "-2-" display
- (3) Rotate it 180° in the same location and press button ON/OFF, "-2-" will flash briefly. Do not move until the unit has completed the calibration.
- (4) Calibration is done. The angle be displayed on the unit is the angle between the calibrated plane and the horizontal plane.



*Any reading on screen in ABS mode shows the angle to water level

"2" ICON FUNCTION

Symbol "" showing how to adjust the surface to be leveled



Battery Installation

- 1. Make sure the digital angle locator is turned off.
- 2. Remove the battery compartment cover
- 3. Install the new battery following the polarity indication
- 4. Replace the battery cover

Note: Always remove the battery before storing the instrument.